creatline village



Мето

To:Board of DirectorsFrom:Alan Clanin, General ManagerDate:January 21, 2020Subject:Managers Report

1. IT System Server Upgrade -

The old Comet Server has 2 failed or failing drives. This server is the District Domain Controller and has been scheduled for virtualizing to one of the other new District servers. The Aclara Server was chosen to be the new Domain Controller due to the available capacity. During the virtualization process which includes promoting the new Aclara server to a Domain Controller and demoting the Comet Server, it was found that the Aclara Server which handles the automatic meter reading for the District needs to be a stand-alone server and is unable to function as a Domain Controller. The District purchased a used server and had new drives and an operating system installed and has had it configured as the new Domain Controller.

2. Electra Well -

The Electra Well was damaged during the Thanksgiving snow storm. A contractor that plows snow for the County in the Valley of the Moon area hit and sheared off the top of the well head causing it to drop almost 50 feet into the well casing. Upon inspection, the well discharge pipe was found to have threads that were undamaged and may be used for recovery. It is expected that damage has occurred on the well pump/motor combo which will have to be replaced prior to usage. The County has been notified but no claim will be filed until the full extent of the damages are known.